





Certified Inspection Report for: Weedon Bec Parish Council 16 St Mary's Way, Weedon Bec Northamptonshire, NN7 4QL	Our Ref: 1251683 ~ 410419 Contact: Sue Halkett Tel: 01327 341 057 Email: weedonbecpc@btinternet.com	Site Address :- Jubilee Field Bridge Street, Weedon Bec Northamptonshire, NN7 4PN	SHEET 1 of 3
------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------	---------------------------------------------------



DESCRIPTION OF PRODUCT(S) INSPECTED	MAKER & YEAR	RISK RATING	INSPECTION COMMENTS	QTY.	PRODUCT CODE	DESCRIPTION OF PART(S) REQUIRED	UNIT PRICE	TOTAL
Cableway on Safety Grass	Unknown	L	Generally satisfactory but the traveller braking components are wearing					
		L	Monitor wear at the traveller end plates					
		L	Monitor minor damage at the seat edge (<i>dog bite marks evident</i>)					
		M	Monitor the timber condition at the ramp foot grip half round logs					
		L	Recommend regular grounds maintenance at grass surface adjacent to start ramp to combat erosion and reduce potential slip hazards.					
2 x 5-A Side Goal on Grass	Wicksteed	L	Generally satisfactory but recommend regular grounds maintenance at the grass surface					
BMX Dirt Track on Grass	Natural Play	L	Generally satisfactory but recommend regular grounds maintenance at the riding surface, security fence crosses the riding surface					
		L	Monitor timber condition at the division barrier					
2.75m 1 Bay 2 Seat Swing 2 x Flat Seat on Safety Grass	Wicksteed	M	Generally satisfactory but recommend excess links are removed to reduce potential snagging hazards (<i>leave two links only through 'key link' to effect security</i>)					
		M	Safety grass matting is loose, loose tiles, gaps and raised edges could create trip hazards or encourage vandalism, recommend the existing matting is lifted, turf surface is reinstated and the matting is re-laid.			contact sales@wicksteed.co.uk for more information regarding removal & re-laying of safety grass matting		
Pendulum Swing Basket Seat on Safety Grass	Wicksteed 2010		<i>(manufacturer recommends the universal joint / swing support bearing assembly should be replaced every 5 years, the assembly is 'sealed for life' unit and maintenance / repairs to the unit should not be attempted (ref BS EN1176-1:2017 clause 6.1.4.2, last replaced 2017)</i>					
		L	Generally satisfactory but monitor wear at the chain links and basket suspension shackles					
		L	Monitor safety grass condition, especially gaps at joints					
Double Zig-Zag Twister on Safety Grass	Wicksteed 2010	L	Generally satisfactory but monitor wear at the bearings and foundation integrity (<i>ensure the regular greasing of the bearings is included within your maintenance schedule.</i>)					



 	Wicksteed Leisure Ltd Digby St., Kettering Northants, NN16 8YJ Tel: 01536 517 028	INDICATION OF RISK RATING ASSESSMENT			INSPECTED BY :- C. Newell	PARTS SUB TOTAL	£0.00
	H/MH	HIGH & MEDIUM HIGH RISK - See Introductory Notes	DATE :-	15.6.2020	BALANCE C / FORWARD	£0.00	
	M	MEDIUM RISK - See Introductory Notes			PARTS TOTAL EXC. CARRIAGE & VAT. (E&O.E.)	£0.00	
	VL/L	VERY LOW & LOW RISK - See Introductory Notes			ESTIMATE TO FIT PARTS * Based on all works ordered	£0.00	



Certified Inspection Report for: Weedon Bec Parish Council 16 St Mary's Way, Weedon Bec Northamptonshire, NN7 4QL	Our Ref: 1251683 ~ 410419 Contact: Sue Halkett Tel: 01327 341 057 Email: weedonbecpc@btinternet.com	Site Address :- Jubilee Field Bridge Street, Weedon Bec Northamptonshire, NN7 4PN	SHEET 2 of 3
------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------	---------------------------------------------------

DESCRIPTION OF PRODUCT(S) INSPECTED	MAKER & YEAR	RISK RATING	INSPECTION COMMENTS	QTY.	PRODUCT CODE	DESCRIPTION OF PART(S) REQUIRED	UNIT PRICE	TOTAL
Perforated Litter Bin Frame on Grass	Wicksteed	VL	Generally satisfactory but post caps have been removed					
Multi-sports Goal on Tarmac	SMP	M	Generally satisfactory but monitor the fixing security, one fixing is loose (<i>captive threaded fixing has failed</i>) & several manufacturer's fixings have been replaced					
		L	Monitor the paint condition					
		M	Recommend turf surfaces are reinstated at erosion areas and tarmac edging to reduce potential trip hazards, especially within the goal mouth					
Leaning Post on Grass	SMP	L	Generally satisfactory but recommend turf surfaces are reinstated at erosion areas					
2 x Football Goal on Grass (<i>ground sockets</i>)	Forza	L	Generally satisfactory but recommend turf surfaces are reinstated at erosion areas					
		L	Monitor the foundation integrity at the ground sockets					
		M	Recommend redundant security fencing is removed from behind one goal					
7.0m Wavy Slide & Platform on Safety Grass Embankment	Kompan	M	Generally satisfactory but recommend redundant fixing hole at the climbing ramp is capped or sealed to reduce potential finger entrapment hazard (ref BS EN 1176-1:2017, clause 4.2.7.6)					
		L	Recommend turf surfaces are reinstated at exposed soil surfaces					
2 x Park Bench on Concrete Base & Grass	Unknown		Satisfactory condition					
2 x Park Seat on Concrete Base & Grass	Unknown	M	Generally satisfactory but recommend missing top and front rails are replaced at one seat to prevent potential snagging hazards at projecting steel bar.					
		L	Monitor the timber condition at the slats					
		M	Litter hazard within the area at time of inspection, including glass alcohol bottles					

  Wicksteed Leisure Ltd Digby St., Kettering Northants, NN16 8YJ Tel: 01536 517 028	INDICATION OF RISK RATING ASSESSMENT			INSPECTED BY :-	PARTS SUB TOTAL	£0.00
	H/MH	HIGH & MEDIUM HIGH RISK - See Introductory Notes		C. Newell	BALANCE C / FORWARD	£0.00
	M	MEDIUM RISK - See Introductory Notes		DATE :-	PARTS TOTAL EXC. CARRIAGE & VAT. (E&O.E.)	£0.00
	VL/L	VERY LOW & LOW RISK - See Introductory Notes		15.6.2020	ESTIMATE TO FIT PARTS * Based on all works ordered	£0.00



Certified Inspection Report for: Weedon Bec Parish Council 16 St Mary's Way, Weedon Bec Northamptonshire, NN7 4QL			Our Ref: 1251683 ~ 410419 Contact: Sue Halkett Tel: 01327 341 057 Email: weedonbecpc@btinternet.com			Site Address :- Jubilee Field Bridge Street, Weedon Bec Northamptonshire, NN7 4PN		SHEET 3 of 3
DESCRIPTION OF PRODUCT(S) INSPECTED	MAKER & YEAR	RISK RATING	INSPECTION COMMENTS	QTY.	PRODUCT CODE	DESCRIPTION OF PART(S) REQUIRED	UNIT PRICE	TOTAL
Brick Encased Litter Bin on Grass Dig Litter Bin Post Mounted General	Unknown	L M M MH M	Generally satisfactory but monitor weather damaged at bricks & mortar Bin full and black rubbish bags stacked in front of the wall at time of inspection Satisfactory condition The provision of a sign (pictogram) is recommended giving the following information: a) General emergency telephone number b) Telephone number to contact maintenance personnel c) Name of the playground d) Address of the playground e) Other relevant local information, if applicable (ref: BS EN 1176-7:2008 clause 8.2.4) Access by dogs is not physically prohibited recommend your routine inspection includes monitoring for and removal of animal faeces. (Litter (animal droppings) order 1991 of The Environment Protection Act 1990 requires public walks and pleasure grounds to be free of animal faeces) Recommend a comprehensive survey is carried out on trees within and around the play area by an arboreal specialist to ascertain their health and take appropriate remedial action where required Unrestricted access to open water source, parental supervision recommended at all times. Unrestricted access to car parking area, parental supervision recommended at all times.			<i>A wide range of signs are available, visit www.wicksteed.co.uk or contact sales@wicksteed.co.uk for more information</i> 		
 Wicksteed Leisure Ltd Digby St., Kettering Northants, NN16 8YJ Tel: 01536 517 028 www.wicksteed.co.uk			INDICATION OF RISK RATING ASSESSMENT H/MH HIGH & MEDIUM HIGH RISK - See Introductory Notes M MEDIUM RISK - See Introductory Notes VL/L VERY LOW & LOW RISK - See Introductory Notes		INSPECTED BY :- C. Newell DATE :- 15.6.2020		PARTS SUB TOTAL £0.00 BALANCE C / FORWARD £0.00 PARTS TOTAL EXC. CARRIAGE & VAT. (E&O.E.) £0.00 ESTIMATE TO FIT PARTS * Based on all works ordered £0.00 TOTAL COST OF WORKS, EXC VAT £0.00	

Certified Inspection Report for: Weedon Bec Parish Council 16 St Mary's Way, Weedon Bec Northamptonshire, NN7 4QL			Our Ref: 1251683 ~ 410419 Contact: Sue Halkett Tel: 01327 341 057 Email: weedonbecpc@btinternet.com			Site Address :- Croft Way Recreation Ground Weedon Bec (rear of Village Hall) Northamptonshire, NN7 4QW		SHEET 1 of 4
DESCRIPTION OF PRODUCT(S) INSPECTED	MAKER & YEAR	RISK RATING	INSPECTION COMMENTS	QTY.	PRODUCT CODE	DESCRIPTION OF PART(S) REQUIRED	UNIT PRICE	TOTAL
Crazy Twister on Safety Grass	Wicksteed 2010		Satisfactory condition (<i>ensure that regular greasing of bearings is included within your annual maintenance schedule.</i>)					
Robinia Giant Rope Swing on Safety Grass	Kompan		Satisfactory condition					
Pick Up Sticks Climbing Frame on Safety Grass	Unknown		Satisfactory condition (<i>the unit lacks manufacturer's identification ref BS EN 1176-1:2017, clause 7.1, this information might be required for future reference when procuring spare parts or maintenance information</i>)					
2.4m Basket Swing on Safety Grass	Kompan	M	Generally satisfactory but recommend basket is cleaned to remove bird faeces prior to opening the play area to the public					
Spinning Dish on Safety Grass	Kompan		Satisfactory condition					
General: Timber Products			Monitor timber condition, climatic conditions are likely to affect the timber appearance (air splits etc.), these would not normally affect structural integrity but loose material should be removed or made safe to reduce potential splinter or abrasion hazards (<i>do not fill splits as this can lead to further damage during the natural expansion and contraction process</i>)					
2 x Talking Flower on Grass	Wicksteed 2010	L	Generally satisfactory but monitor minor vandalism at one petal panel, recommend rough edges are removed					
Mystical World Multi-play Unit on Safety Grass	Wicksteed 2010	L	Generally satisfactory but monitor minor vandalism at the 'Spooky Pairs' game panel, one spinning panel spindle has been slightly deformed					
2.3m 1 Bay 2 Seat Swing 2 x Flat Seat on Safety Grass	Wicksteed 2010	M	Generally satisfactory but one seat is worn & damaged, recommend the affected seat is replaced as soon as possible	1	5901F113	Flat Rubber Seat c/w Fixings Labour cost to fit seat	£44.00 See sheet 2	£44.00
		L	Monitor wear at the chain links					
  Wicksteed Leisure Ltd Digby St., Kettering Northants, NN16 8YJ Tel: 01536 517 028			INDICATION OF RISK RATING ASSESSMENT H/MH HIGH & MEDIUM HIGH RISK - See Introductory Notes M MEDIUM RISK - See Introductory Notes VL/L VERY LOW & LOW RISK - See Introductory Notes		INSPECTED BY :- C. Newell DATE :- 15.6.2020		PARTS SUB TOTAL £44.00 BALANCE C / FORWARD £0.00 PARTS TOTAL EXC. CARRIAGE & VAT. (E&O.E.) £44.00 ESTIMATE TO FIT PARTS * Based on all works ordered See sheet 4	

Certified Inspection Report for: Weedon Bec Parish Council 16 St Mary's Way, Weedon Bec Northamptonshire, NN7 4QL			Our Ref: 1251683 ~ 410419 Contact: Sue Halkett Tel: 01327 341 057 Email: weedonbecpc@btinternet.com			Site Address :- Croft Way Recreation Ground Weedon Bec (rear of Village Hall) Northamptonshire, NN7 4QW			SHEET 2 of 4	
DESCRIPTION OF PRODUCT(S) INSPECTED	MAKER & YEAR	RISK RATING	INSPECTION COMMENTS	QTY.	PRODUCT CODE	DESCRIPTION OF PART(S) REQUIRED	UNIT PRICE	TOTAL		
Spiro-whirl Roundabout on Wet Pour	Wicksteed 2010		Satisfactory condition (<i>ensure that regular greasing of bearings is included within your annual maintenance schedule.</i>)							
1.75m 1 Bay 2 Seat Swing 2 x Cradle Seat on Tiles	Wicksteed	M	Generally satisfactory but one seat is worn & damaged, recommend the affected seat is replaced (<i>perished or flaking rubber could cause choking if swallowed</i>)	1	5901-048	Single Tier Rubber Cradle Seat (2007)	£145.00	£145.00		
		M	Recommend damaged or missing surface edging is replaced	18	L-Maint	3" x 2" Lin Mts Timber edging Labour cost to replace timber edging & fit seats*	£9.50 £270.00	£171.00		
3.4m Pedestal Slide on Tiles	Wicksteed		Generally satisfactory but fails BS EN 1176 design criteria at the following areas:-							
		L	Fails Head & Torso probe test at the hand and guardrails (ref BS EN 1176-1:2017, clause 4.2.7.2), no action recommended at present.							
		L	Fails Toggle test at chute entrance (BS EN 1176-1:2017, clause 4.2.7.3, no action recommended at present							
		L	Fails Stair criteria (BS EN 1176-1:2017: clause 4.2.9.2), no action recommended at present							
		M	Recommend painting of this unit is included within your maintenance schedule (<i>note: ensure surface coatings are free of harmful contents to avoid potential toxic hazards, ref BS EN 1176-1:2017, clause 4.1.1</i>)	2	2820-002	Primer Per Litre	£20.00	£40.00		
			Loose or flaking paint could create infection (<i>dermatitis</i>) hazards	1	2820-004	Red Gloss Paint Per Litre	£20.00	£20.00		
				1	2820-041	Light Blue Gloss Paint Per Litre	£20.00	£20.00		
				1	2820-008	Yellow Gloss Paint Per Litre	£20.00	£20.00		
		L	Monitor the gaps at tile joints where excessive gaps or lifting tiles could create trip hazards.			Labour cost to paint slide*	£450.00			
		L	Monitor the timber condition at the tile retention edging							
Speed Bike Spring Mobile on Grass	Ledon		Generally satisfactory but fails BS EN 1176 design criteria at the following areas:-							
		L	Fails foot rest requirements for spring mobiles (ref BS EN 1176-6: 2008 clause 4.6), no action recommended at present.							
		M	Recommend turf surfaces are reinstated at erosion areas to reduce potential slip and impact hazards (<i>note: ground fixing plate and clamp assembly set below the grass surface</i>)							
Link Non Bump See Saw on Safety Grass	Wicksteed 2010		Satisfactory condition							
  Wicksteed Leisure Ltd Digby St., Kettering Northants, NN16 8YJ Tel: 01536 517 028				INDICATION OF RISK RATING ASSESSMENT H/MH HIGH & MEDIUM HIGH RISK - See Introductory Notes M MEDIUM RISK - See Introductory Notes VL/L VERY LOW & LOW RISK - See Introductory Notes			INSPECTED BY :- C. Newell DATE :- 15.6.2020		PARTS SUB TOTAL £416.00 BALANCE C / FORWARD £44.00 PARTS TOTAL EXC. CARRIAGE & VAT. (E&O.E.) £460.00 ESTIMATE TO FIT PARTS * Based on all works ordered See sheet 4	

Certified Inspection Report for: Weedon Bec Parish Council 16 St Mary's Way, Weedon Bec Northamptonshire, NN7 4QL	Our Ref: 1251683 ~ 410419 Contact: Sue Halkett Tel: 01327 341 057 Email: weedonbecpc@btinternet.com	Site Address :- Croft Way Recreation Ground Weedon Bec (rear of Village Hall) Northamptonshire, NN7 4QW	SHEET 3 of 4
------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------



DESCRIPTION OF PRODUCT(S) INSPECTED	MAKER & YEAR	RISK RATING	INSPECTION COMMENTS	QTY.	PRODUCT CODE	DESCRIPTION OF PART(S) REQUIRED	UNIT PRICE	TOTAL
Spring Platform on Grass	Miracle	M	Generally satisfactory but monitor the plastic coating at the platform edge, further deterioration could result in snagging or corrosion hazards, no remedial action possible with this type of coating.					
4 Way Spring Mobile on Safety Grass	Miracle	VL	Generally satisfactory but monitor the paint condition at the centre plate					
Climbing Frame on Safety Grass	Miracle		Satisfactory condition					
Windsor Picnic Table on Grass	Wicksteed	M	Generally satisfactory but recommend timber slats are rubbed down and treated to maintain weather protection, monitor damage at centre slat and recommend excess bolt threads at one seat slat are trimmed to reduce potential snagging hazards (<i>non-manufacturer's fixings</i>)					
		M	Monitor ground fixing & foundation integrity and recommend ground and turf levels are built up around the base fixing plates to reduce potential trip hazards					
3 x Timber Bench (2 outside area) on Grass	Unknown	L	Generally satisfactory but monitor the timber condition & foundation integrity, no wood rot evident but could be present below surface level					
Litter Bin Post Mounted	Unknown		Satisfactory condition					
Fence	Unknown		Satisfactory condition					
Vehicle Access Gate	Unknown		Satisfactory condition, locked at time of inspection					
Single Gate (bottom of field)	Unknown		Satisfactory condition, locked at time of inspection					
Single Gate (top of field)	Unknown		Satisfactory condition, locked at time of inspection					



 	Wicksteed Leisure Ltd Digby St., Kettering Northants, NN16 8YJ Tel: 01536 517 028	INDICATION OF RISK RATING ASSESSMENT H/MH HIGH & MEDIUM HIGH RISK - See Introductory Notes M MEDIUM RISK - See Introductory Notes VL/L VERY LOW & LOW RISK - See Introductory Notes	INSPECTED BY :- C. Newell DATE :- 15.6.2020	PARTS SUB TOTAL BALANCE C / FORWARD PARTS TOTAL EXC. CARRIAGE & VAT. (E&O.E.) ESTIMATE TO FIT PARTS * Based on all works ordered	£0.00 £460.00 £460.00 See sheet 4
------------------------------------------------------------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------



Certified Inspection Report for: Weedon Bec Parish Council 16 St Mary's Way, Weedon Bec Northamptonshire, NN7 4QL			Our Ref: 1251683 ~ 410419 Contact: Sue Halkett Tel: 01327 341 057 Email: weedonbecpc@btinternet.com			Site Address :- Croft Way Recreation Ground Weedon Bec (rear of Village Hall) Northamptonshire, NN7 4QW			SHEET 4 of 4
------------------------------------------------------------------------------------------------------------------------------------------	--	--	------------------------------------------------------------------------------------------------------------------------------------------	--	--	-------------------------------------------------------------------------------------------------------------------------	--	--	---------------------------------------------------

DESCRIPTION OF PRODUCT(S) INSPECTED	MAKER & YEAR	RISK RATING	INSPECTION COMMENTS	QTY.	PRODUCT CODE	DESCRIPTION OF PART(S) REQUIRED	UNIT PRICE	TOTAL
General			The provision of a sign (pictogram) is recommended giving the following information: a) General emergency telephone number b) Telephone number to contact maintenance personnel c) Name of the playground d) Address of the playground e) Other relevant local information, if applicable (ref: BS EN 1176-7:2008 clause 8.2.4)			<i>A wide range of signs are available, visit www.wicksteed.co.uk or contact sales@wicksteed.co.uk for more information</i>		



  Wicksteed Leisure Ltd Digby St., Kettering Northants, NN16 8YJ Tel: 01536 517 028 www.wicksteed.co.uk		INDICATION OF RISK RATING ASSESSMENT H/MH HIGH & MEDIUM HIGH RISK - See Introductory Notes M MEDIUM RISK - See Introductory Notes VL/L VERY LOW & LOW RISK - See Introductory Notes			INSPECTED BY :- C. Newell DATE :- 15.6.2020		PARTS SUB TOTAL BALANCE C / FORWARD PARTS TOTAL EXC. CARRIAGE & VAT. (E&O.E.) ESTIMATE TO FIT PARTS * Based on all works ordered TOTAL COST OF WORKS, EXC VAT		£0.00 £460.00 £460.00 £720.00 £1,180.00
------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--	--	--------------------------------------------------------------------	--	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--	----------------------------------------------------------------------------------------

Certified Inspection Report for: Weedon Bec Parish Council 16 St Mary's Way, Weedon Bec Northamptonshire, NN7 4QL			Our Ref: 1251683 ~ 410419 Contact: Sue Halkett Tel: 01327 341 057 Email: weedonbecpc@btinternet.com		Site Address :- Cavalry Fields Play Area Fusilier Drive, Weedon, NN7 4TH			SHEET 1 of 2	
DESCRIPTION OF PRODUCT(S) INSPECTED	MAKER & YEAR	RISK RATING	INSPECTION COMMENTS	QTY.	PRODUCT CODE	DESCRIPTION OF PART(S) REQUIRED	UNIT PRICE	TOTAL	
2.25m 1 Bay 2 Seat Swing 1 x Flat & 1 x Cradle Seat on Tiles	SMP	L	Generally satisfactory but monitor paint condition at the top bar and cradle seat frames						
		L	Monitor the gaps at tile joints where excessive gaps or lifting tiles could create trip hazards.						
		L	Recommend soil and seed are added at the surface edging to reduce potential trip hazards						
2.4m Toddler's Slide on Tiles	SMP	L	Generally satisfactory but step design would prevent use by younger children without assistance, in addition, monitor wear at the step panels						
		L	Monitor the gaps at tile joints where excessive gaps or lifting tiles could create trip hazards.						
Hippo Spring Mobile on Tiles	SMP		Generally satisfactory but fails BS EN 1176 design criteria at the following areas:-						
		L	Fails hand grip & foot rest requirements for spring mobiles (ref BS EN 1176- 6: 2017 clauses 4.6 & 4.7), no action recommended at present.						
		VL	Seat fixing insert caps have been removed						
		L	Monitor the gaps at tile joints where excessive gaps or lifting tiles could create trip hazards.						
Park Bench on Grass	Record	L	Satisfactory condition but located close to fence & could encourage climbing						
		L	Monitor the paint condition						
Litter Bin on Grass	Unknown		Satisfactory condition.						
Single Gate	Unknown	L	Generally satisfactory but fails Head & Neck probe test (ref BS EN 1176-1:2017, clause 4.2.7.2) between the railings and could result in entrapment hazard, no remedial action possible with fence design						
		M	Recommend turf surface is reinstated within the entrance to reduce potential trip hazards at the raised kerb edging Gate secured at time of inspection						
  Wicksteed Leisure Ltd Digby St., Kettering Northants, NN16 8YJ Tel: 01536 517 028				INDICATION OF RISK RATING ASSESSMENT H/MH HIGH & MEDIUM HIGH RISK - See Introductory Notes M MEDIUM RISK - See Introductory Notes VL/L VERY LOW & LOW RISK - See Introductory Notes		INSPECTED BY :- C. Newell DATE :- 15.6.2020		PARTS SUB TOTAL BALANCE C / FORWARD PARTS TOTAL EXC. CARRIAGE & VAT. (E&O.E.) ESTIMATE TO FIT PARTS * Based on all works ordered	£0.00 £0.00 £0.00 £0.00

DESCRIPTION OF PRODUCT(S) INSPECTED			MAKER & YEAR	RISK RATING	INSPECTION COMMENTS	QTY.	PRODUCT CODE	DESCRIPTION OF PART(S) REQUIRED	UNIT PRICE	TOTAL
Certified Inspection Report for: Weedon Bec Parish Council 16 St Mary's Way, Weedon Bec Northamptonshire, NN7 4QL			Our Ref: 1251683 ~ 410419 Contact: Sue Halkett Tel: 01327 341 057 Email: weedonbecpc@btinternet.com			Site Address :- Croft Way Recreation Ground Weedon Bec (rear of Village Hall) Northamptonshire, NN7 4QW			SHEET 2 of 2	
Fence Dog Litter Bin (outside area) Post Mounted General				L	Generally satisfactory but fails Head & Neck probe test (ref BS EN 1176-1:2017, clause 4.2.7.2) between the railings and could result in entrapment hazard, no remedial action possible with fence design Satisfactory condition. The provision of a sign (pictogram) is recommended giving the following information: a) General emergency telephone number b) Telephone number to contact maintenance personnel c) Name of the playground d) Address of the playground e) Other relevant local information, if applicable (ref: BS EN 1176-7:2008 clause 8.2.4)			<i>A wide range of signs are available, visit www.wicksteed.co.uk or contact sales@wicksteed.co.uk for more information</i>		
  Wicksteed Leisure Ltd Digby St., Kettering Northants, NN16 8YJ Tel: 01536 517 028 www.wicksteed.co.uk			INDICATION OF RISK RATING ASSESSMENT H/MH HIGH & MEDIUM HIGH RISK - See Introductory Notes M MEDIUM RISK - See Introductory Notes VL/L VERY LOW & LOW RISK - See Introductory Notes			INSPECTED BY :- C. Newell DATE :- 15.6.2020		PARTS SUB TOTAL BALANCE C / FORWARD PARTS TOTAL EXC. CARRIAGE & VAT. (E&O.E.) ESTIMATE TO FIT PARTS * Based on all works ordered TOTAL COST OF WORKS, EXC VAT		£0.00 £0.00 £0.00 £0.00 £0.00

